



SA Water OCUs Performance Assessments

Keywords: Odour assessment and measurement

Presenters: Paul Sproules¹, Heath Georgeff²

¹ Stantec Australia, NSW, Australia

² SA Water, SA, Australia

SA Water OCUs Performance Assessments

WWPS Sites:

WWPS184 - Reliance Rd
Hallet Cove

WWPS282 - Capella Dr
Hallet Cove


WWPS021 - Capelli Rd
Wingfield

WWPS17 - Gertrude St
Port Pirie

Trunk Sewer sites:

OCU1 - Teasdale Cr
Parafield Gardens

OCU2 - Shepherdson Rd
Parafield Gardens



SA Water OCUs Performance Assessments

WWPS Sites:

WWPS184 - Reliance Rd
Hallet Cove

WWPS282 - Capella Dr
Hallet Cove

WWPS021 - Capelli Rd
Wingfield

WWPS17 - Gertrude St
Port Pirie

Trunk Sewer sites:


OCU1 - Teasdale Cr
Parafield Gardens

OCU2 - Shepherdson Rd
Parafield Gardens



OCUs Performance Assessments

Prepare report with collated data, observations and finding with recommendations for improvements ensuring optimal performance



SA Water OCUs Performance Assessments

WWPS Sites:

WWPS184 - Reliance Rd
Hallet Cove

WWPS282 - Capella Dr
Hallet Cove

WWPS021 - Capelli Rd
Wingfield

WWPS17 - Gertrude St
Port Pirie

Trunk Sewer sites:

OCU1 - Teasdale Cr
Parafield Gardens

OCU2 - Shepherdson Rd
Parafield Gardens



Two site visits were made:

17th April 2025

Condition assessments
(the five metropolitan sites)

20th to 22nd May 2025

Performance assessments
(all six sites)


WWPS Sites



Reliance Rd, Hallett Cove - 2016

2 x organic biofilters


1 x activated carbon filter (ACF)



Capella Ave, Hallett Cove - 2014

1 x organic biofilter

1 x ACF




Capelli Rd, Wingfield - 2012

2 x organic biofilters

1 x ACF



Condition Assessments



WWPS184 OCU, Reliance Road, Hallett Cove

Performance Assessment

Condition	Performance
GOOD	GOOD


KEY PARAMETER	MEASURED	TARGET
Airflow (m ³ /hr)	774	2,398
pH	Not measured	N/A
dP* (Pa)	273	353
H ₂ S* (ppm)	0.48	<1
% efficiency	92	>90



- H₂S inlet: 6 ppm.
- Inlet volatile organic compounds (VOC): 1.5 ppm.
- H₂S after biofilters: 0.48 ppm (92% removal) via spot sample measurements.
- H₂S after carbon: 385 ppb

Recommended actions

- Consideration of network ventilation and possible rectification of restricted airflow through collecting pump station manhole
- Renewal of blocked drains



WWPS282 OCU, Capella Avenue, Hallett Cove

Performance Assessment


KEY PARAMETER	MEASURED	TARGET
Airflow (m ³ /hr)	1080	1080
pH	-	-
dP across BF (Pa)	160	N/A
H ₂ S after BF (ppm)	0.3	<1
% efficiency	97	>90

- Inlet H₂S: 9.7 ppm
- Inlet VOCs: 1.5 ppm
- Outlet H₂S (post biofilter): 0.3 ppm (97% removal)
- Outlet H₂S (post carbon): 570 ppb

Recommended actions

- Investigate sump pump performance issue leading to flooding of sump.
- Fix blocked duct drain after the biofilter.
- Monitor carbon bed odour breakthrough and replace when required.

Condition	Performance
FAIR	GOOD



WWPS021 OCU, Capelli Road, Wingfield

Performance Assessment

KEY PARAMETER	MEASURED	TARGET
Airflow (m ³ /hr)	1,501	2,160
pH	-	-
dP across BF1 (Pa)	600	<600
dP across BF2 (Pa)	720	<600
H ₂ S after BF (ppm)	3	<4.6
% efficiency	94	>90

Recommended actions

- Consideration of the restriction of foul air extraction from the sewer.
- Other items:
 - Replacement of the ductwork with FRP ductwork
 - Remedy of various leakage points
 - Renewal of the humidity sensors
 - Renewal of the H₂S sample pump
 - Renewal of the irrigation rotameters

Condition	Performance
FAIR	FAIR



WWPS17 OCU, Gertrude Road, Port Pirie



OCU installed in 2016

1 x organic biofilter

1 x ACF

No complaints received from this site

Condition	Performance
POOR	POOR




KEY PARAMETER	MEASURED	TARGET
Airflow (m ³ /hr)	159	509 - 636
pH	-	-
dP across BF (Pa)	375	-
dP across ACF (Pa)	20	-
H ₂ S after BF (ppm)	1.6	<1.2
BF % efficiency	87	>90
H ₂ S after carbon (ppb)	400	0
ACF % efficiency	75	>99

Recommended actions

- Replacement of the biofilter media and checking of the irrigation rate and cycle.
- Replacement of the carbon media
- Repair of the hole in the site perimeter fence
- Replacement of the fan mounting
- Renewal of ductwork and expansion joints
- Rectification of the biofilter drain

Trunk Sewer sites: Parafield Gardens

Teasdale Crescent and Shepherdson Road



OCU1, Teasdale Crescent, Parafield Gardens

Performance Assessment

KEY PARAMETER	MEASURED	TARGET
Airflow (m ³ /hr)	836	1,750 - 2,250
pH	2.68	1 - 3
dP across BTF (kPa)	1.05	<1.5
dP across BF (kPa)	0.6	<1.5
dP across ACF (kPa)	0.41	<1.5
H ₂ S after BTF (ppm)	1.8	<3
BTF % efficiency	>99	>99
H ₂ S after BF (ppm)	0.1	<0.2
BF % efficiency	95	>90

Recommended actions

- Renewal of:
 - leaking sampling ports
 - pressure indicators
 - dosing pump mounting and corroded cable tray
- Removal of an intrusive tree branch at top platform.
- Calibration of the Dräger Polytrons
- Consideration of sewer corrosion. High septicity is recommended to be addressed to prolong sewer life
- Although H₂S removal is good, further assessment of possible BTF media compaction will determine if DP continues to rise leading to potential biomass degradation putting performance pressures on the system



Condition	Performance
FAIR	FAIR

OCU2, Shepherdson Road, Parafield Gardens

Performance Assessment

KEY PARAMETER	MEASURED	TARGET
Airflow (m ³ /hr)	412	1,750-2,250
pH	3.26	1-3
dP across BTF (kPa)	2.58	<1.5
dP across BF (kPa)	0.08	<1.5
dP across ACF (kPa)	0.23	<1.5
H ₂ S after BTF (ppm)	30	<7.5
BTF % efficiency	96	>99
H ₂ S after BF (ppm)	0.6	<3
BF % efficiency	98	>90

Recommended actions

- High sewer septicity to be addressed to prolong sewer life
- Calibration of the Dräger Polytron units
- Renewal of:
 - leaking sampling ports, pressure indicators
 - bypass duct condensate accumulation
 - repair delaminating vessel rib at rear of biofilter
- Immediate attention to compacted BTF media preventing full airflow through BTF
- Signs indicate biomass degradation and increased activated carbon media usage



Condition	Performance
FAIR	POOR



No complaints received from this site
Issues related to undraw of air from the sewer

Supporting Cast



thanking:
Tharushi Silva
Matt Scott-Toms




Wider implications of findings

Where local residents were exposed to undertreated sewer gases

Sites exposed to higher OPEX

Sites with elevated corrosion rates





Planning improvements

Data and observations for
planned interventions

Quantifiable
evidence to
improve internal
systems





Overcoming maintenance challenges

Identify
maintenance
challenges

Resourcing of
available staff

Identify operator training gaps

- additional training later this year
- different operating needs of the sites





Conclusions

Provided data and evidence of performance issues

Emphasised the need for better informed and trained operators

Increased awareness of issues for more effective plant operations





Any questions?

Heath Georgeff – SA Water |
heath.georgeff@sawater.com.au

Paul Sproules – Stantec
paul.sproules@stantec.com



Working together

Communities are fundamental. Whether around the corner or across the globe, they provide a foundation, a sense of place and of belonging. That's why at Stantec, we always design with community in mind.

We care about the communities we serve—because they're our communities too. We're designers, planners, engineers, scientists, and project managers, innovating together at the intersection of community, creativity, and client relationships. Balancing these priorities results in projects that advance the quality of life in communities across the globe. Stantec trades on the Toronto Stock Exchange (TSX) and the New York Stock Exchange (NYSE) under the symbol STN.

Australian offices:

Adelaide, Albany, Brisbane, Busselton, Gold Coast, Melbourne, Perth, Rockhampton, Sydney

New Zealand offices:

Alexandra, Auckland, Balclutha, Christchurch, Dunedin, Gisborne, Greymouth, Hamilton, Hastings, Napier, Nelson, Palmerston North, Queenstown, Tauranga, Wellington, Whangārei

Connect with us



[Stantec.com](https://www.stantec.com)