



Repair broken wooden posts

Manufactured in Australia

Ocloc V - Long term fix for broken wooden posts

Material: G450 High tensile steel for strength

Coating: GALFAN Coating 5% Aluminium, Rare Metals, 95% Zinc, the ultimate in corrosive resistant coating for durability

Thickness: CV 1.6mm thick Galfan

BV 1.8mm thick Galfan

Length: Available in 900mm 1.5m, 1.2m , 2.4m

Ocloc V fits onto the round or flat, on a half round post

No sharp edges, ideal for under vine management

No need for new toxic replacement posts

No new wooden posts, reduces your vineyards carbon footprint

All Ocloc products are carbon offset

Maintain your organic status

You will not have to cut staples or remove plastic clips

No more posts to the broken post graveyard

Ocloc V application requires a side by side, 4-wheeler or equivalent, petrol rammer, impact driver or drill

Find broken post repair with Ocloc V with one pass

4 x 75mm shark tooth screws supplied

Ocloc V is an inexpensive install that alleviates the expense of tedious traditional treated wooden post replacement and the ecological footprint legacy they create




Lower clip position, lifting wire.




Round side


Flat side




Half round post fix on round side



Half round post fix on flat side



Full round post fix on round side



Quarter round post fix on flat sides

Ocloc products are carbon neutral — 100% carbon offset —



For further details please contact

Ocloc au: Nigel Catt 0418 832 967 • nigel@ocloc.com.au

Ocloc nz: Phil Gleeson 0272 759 057 • office@oclocnz.co.nz

